

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6






FIG. 7



Read Request



Write Request

FIG. 8




FIG. 9




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15





FIG. 16



11020252

FIG. 17




FIG. 18




FIG. 19







FIG. 20 A



Enlarged View of Perforation

FIG. 20 B

FIG. 21 A




Enlarged View of Connecting
Portion of Perforation

FIG. 21 B

Enlarged View of Gap
Portion of Perforation

FIG. 21 C

FIG. 22 A





Enlarged View of Connecting
Portion of Perforation

FIG. 22 B

Enlarged View of Gap
Portion of Perforation

FIG. 22 C

FIG. 23 A



Enlarged View of Perforation

FIG. 23 B